


227 Industrial Drive Harbor Beach Mi 48441
Phone:989-479-0444 Fax:989-479-9844

IMPORTANT

Installation of this repair harness requires attention to detail. It's always best practice to install this repair harness 1 wire at a time. Wire coatings can discolor overtime so always match your wires based on pin location, not wire color. The pictures below are an example of correct pin layout and color match vs a used harness.



DHD 100-449 Repair Harness for 2001-2005 Allison 1 Plug NSBU